

Figure 1

HLL ID	Rule Set	Brief Explanation
HLL001	(LogP6000 or LogP6001 or LogP6002) from 2 or more phones.	Two or more phones are not receiving full services
HLL002	LogPBX2000 + LogC3000	Loss of services. Something is wrong with PBX2
HLL003	HLL001 + HLL002	Loss of services. Something is wrong with T1 trunk.

Figure 2

Log ID	Time Generated	Brief Description	Execution Set
LogP6000	Feb. 29, 2000 14:23:04:12	No dial tone for phone P2.	NONE
LogPBX2000	Feb. 29, 2000 14:23:04:17	PBX 1 is not receiving full services.	Page technician.Send Medium level alarm to monitoring application.
LogP6001	Feb. 29, 2000 14:23:04:27	Reduction of features available for phone P4.	- If phone has LED display, display "not fully functional" on LED display.
LogC3000	Feb. 29, 2000 14:23:04:29	Client C1 cannot give services to phones.	- Do self-diagnostic of network services.
HLL002	Feb. 29, 2000 14:23:04:32	Loss of services on network.	 Page two technicians. Send High level alarm to monitoring application. Re-route traffic to backup PBX.
LogP6002	Feb. 29, 2000 14:23:05:00	No services available for phone P1.	NONE
HLL001	Feb. 29, 2000 14:23:05:03	PBX 1 is not providing full services to phones.	- Page technician Send Medium level alarm to monitoring application.
HLL003	Feb. 29, 2000 14:23:05:05	Trunk T1 is unavailable.	 - Page ten technicians. - Send Critical level alarm to monitoring application. - Use another trunk if available.

Figure 3





Figure 4

Har offer H H Harl



BEGIN

Figure 5

The Hard type upper the Hard that the state of the three than the table and tabl